



All Out Waste Management
2941 VT Route 7A
Shaftsbury VT, 05262
alloutwaste@comcast.net

Septic Inspection Report

Name of person requesting inspection

Tabetha Kanter

Property Address:

Arlington Inn

Inspection Date:

03/26/2026

Was the septic tank pumped?

Yes

Tank location

One tank on left side and one tank on right side of inn

Tank location photo



Photo



Photo



All Out Waste Management
2941 VT Route 7A
Shaftsbury VT, 05262
alloutwaste@comcast.net

Photo

Type of System

Type of onsite disposal

Septic tank with drywell

Construction of tank

Concrete

Condition of tank

Good

Tank capacity

left tank is 1000 gallons, right tank is 500 gallons

Does system have a pump station?

No

Does pump station function properly?

N/A

Leaching system was found to
be in working order

Observations

Prior to pumping, was the liquid level above the outlet tee?

No

While pumping the tank, did effluent flow back into tank from
absorption field?

No

Was there a water flow test?

Yes

Did the water flow test pass?

Yes

Visual inspection was requested by:

owner

Visual inspection found:

Both tanks to be in working condition. Drywell are good.

Camera inspection was requested by:

owner

The camera found:

Left side tank- inlet and outlet pipes are cast iron and in working condition. Right side tank- inlet and outlet are cast iron and in working condition.



All Out Waste Management
2941 VT Route 7A
Shaftsbury VT, 05262
alloutwaste@comcast.net

Determinations

Does the septic system pass?

Yes

The septic system is currently:
functioning and in good order

Repairs are needed as follows:

Recommendations:

Pump every 2 years.

Our septic system inspection is not a warranty. Proper care is required to maintain functionality. Regular maintenance is recommended.

The undersigned cannot guarantee the continued acceptability of the septic system due to unpredictable factors, which could later determine the life or code compliance of the system.

Inspector's / Sanitarian's Signature