



**All Out Waste Management**  
**2941 VT Route 7A**  
**Shaftsbury VT, 05262**  
**alloutwaste@comcast.net**

## Septic Inspection Report

Name of person requesting inspection

Tabetha Kanter

Property Address:

Arlington Inn  
Cottage

Inspection Date:

03/26/2026

Was the septic tank pumped?

Yes

Tank location

Behind house

Tank location photo



Photo

Photo



Photo

## Type of System

Type of onsite disposal

Septic tank with standard leachfield

Construction of tank

Concrete

Condition of tank

Good

Tank capacity

1000 Gallons



**All Out Waste Management**  
**2941 VT Route 7A**  
**Shaftsbury VT, 05262**  
**alloutwaste@comcast.net**

**Does system have a pump station?**

No

**Does pump station function properly?**

N/A

**Leaching system was found to  
be in working order**

## Observations

**Prior to pumping, was the liquid level above the outlet tee?**

No

**While pumping the tank, did effluent flow back into tank from  
absorption field?**

No

**Was there a water flow test?**

Yes

**Did the water flow test pass?**

Yes

**Visual inspection was requested by:**

owner

**Visual inspection found:**

Tank to be in working condition.

**Camera inspection was requested by:**

owner

**The camera found:**

Inlet and outlet pipes are PVC and in working  
condition.



**All Out Waste Management**  
**2941 VT Route 7A**  
**Shaftsbury VT, 05262**  
**alloutwaste@comcast.net**

## Determinations

**Does the septic system pass?**

Yes

**The septic system is currently:**  
functioning and in good order

Repairs are needed as follows:

**Recommendations:**

Pump every 3 years.

Our septic system inspection is not a warranty. Proper care is required to maintain functionality. Regular maintenance is recommended.

The undersigned cannot guarantee the continued acceptability of the septic system due to unpredictable factors, which could later determine the life or code compliance of the system.

**Inspector's / Sanitarian's Signature**