



(915)317-5062 office | AAAInspection.net

SEWER SCOPE INSPECTION

Inspection Address:

1207 E Rio Grande Ave
El Paso, TX 79902

How We Inspect:

The Client has requested a Sewer Scope Inspection to inspect the condition of the structure sewer/waster line(s) and to identify components in need of immediate repair. The inspection will include the following: a proper access into the sewer line will be obtained, a camera device is then inserted into the sewer line. The evaluation will be based on visual observations and based upon data collected from the inspection camera equipment. **The inspection is not intended to be technically exhaustive.** AAA Inspections Sewer Scope will provide a summary of observations and unbiased opinions based on the opinion of the inspector. FEET IN VIDEO ARE SHOWN BELOW: MINUS 2FT FROM BASEMENT CLEAN OUT . DUE TO ACTUAL POSITION OF UNIT AND CAMERA HEAD ABOVE GRADE.

Sewer opinion: Camera was inserted in basement cleanout

Findings showed: PVC, CAST IRON & CLAY

1. Lateral line under structure showed to have standing water at approx: 7ft-9ft
2. Lateral line under structure showed to have channeling of cast iron at approx: 15ft-25ft
3. Sewer line toward city showed to be functioning as intended.

Recommendations:

-Recommend plumber correct channeling of cast iron and standing water in PVC

Video link:

[SEWER SCOPE VIDEO](#)