


1909 Tyler Street

Hollywood, FL 33020

Suite 305 - 1,568 RSF



Legend



For more information please contact:

Brady Titcomb

Executive Vice President


brady.titcomb@jll.com

+1 954 653 3222




Hollywood, FL 33020

Suite 402 - 2,012 RSF



Legend



For more information please contact:

Brady Titcomb

Executive Vice President

brady.titcomb@jll.com


+1 954 653 3222



1909 Tyler Street

Hollywood, FL 33020

Suite 501 - 2,956 RSF



Legend



For more information please contact:

Brady Titcomb

Executive Vice President

brady.titcomb@jll.com

+1 954 653 3222



Hollywood, FL 33020


A floor plan of a rectangular room. The room has a central doorway. On the left wall, there is a small square. On the right wall, there is a small square. The room is divided into three sections by the doorway. The left section contains a small square. The middle section contains a doorway. The right section contains a small square. The room is bounded by a thick black line representing the walls. The floor is represented by a light gray area. The ceiling is represented by a light gray area. The walls are represented by a thick black line. The doorway is represented by a break in the wall. The small squares are represented by small black squares.

[illegible]

1909 Tyler Street

Hollywood, FL 33020

Suite 605 - 2,003 RSF



Legend



For more information please contact:

Brady Titcomb

Executive Vice President

brady.titcomb@jll.com


+1 954 653 3222



1909 Tyler Street

Hollywood, FL 33020

Suite 701 - 6,300 RSF



For more information please contact:

Brady Titcomb

Executive Vice President

brady.titcomb@jll.com


+1 954 653 3222



1909 Tyler Street

Hollywood, FL 33020

8th Floor - 8,402 RSF



For more information please contact:

Brady Titcomb

Executive Vice President

brady.titcomb@jll.com

+1 954 653 3222

