




GENERAL NOTES:

1. REPAIR FLOOR TILE IN THE WAITING AND HALL TO MATCH EXISTING
2. EXISTING CEILINGS TO REMAIN
3. PROVIDE DIMMING LIGHTING IN ALL ROOMS
4. PROVIDE NEW FLOOR FINISHES AT ALL CONSULT AND TREATMENT ROOMS

KEY NOTES:

- | | |
|--|---|
| <p>[1] RECONFIGURE EXISTING STOREFRONT DOOR TO PROVIDE SPACE FOR RECEPTION DESK</p> <p>[2] NEW RECEPTION DESK - EXACT CONFIGURATION TO BE CONFIRMED DURING THE DESIGN PHASE</p> <p>[3] FREE-STANDING SCREEN WALL - EXACT CONFIGURATION TO BE CONFIRMED DURING THE DESIGN PHASE</p> <p>[4] NEW WALL - HUNG LAVATORY</p> | <p>[5] NEW CASEWORK WITH LAVATORY - EXACT CONFIGURATION TO BE CONFIRMED DURING THE DESIGN PHASE</p> <p>[6] NEW CASEWORK (NO LAVATORY) - EXACT CONFIGURATION TO BE CONFIRMED DURING THE DESIGN PHASE</p> <p>[7] REMOVE EXISTING DOOR</p> <p>[8] NEW DOOR</p> |
|--|---|