



Unit 3203  
 50' x 51'  
 2,550 sqft

Open to Unit 3101

1 REPAIRED AND  
 TO ORIGINAL  
 CONFIGURATION

1/ SHEATHING  
 FRAMED  
 TYP.

INFILL EXISTING MASONRY DOOR  
 OPENING HALF LEVEL BELOW  
 TO MATCH ADJACENT FINISHES  
 (SEE ELEVATION 19A3-15)

NEW WINDOWS AT  
 REPAIRS OPENINGS

INFILL RAFT AREA w/ WOOD  
 FRAMING TO BE FLUSH w/  
 EXISTING FLOOR LEVEL

EXISTING DOORS TO BE  
 REPAIRS AND RETURN IN  
 FIELD POSITION

**FITNESS CTR.**

REPAIRS/RESTORE  
 DAMAGED MASONRY WALL

NEW CONC STAIRS  
 w/ METAL RAILINGS

EXISTING  
 FLUSH CONC  
 RAILING  
 TO REMAIN

STAIRS