




FOR SALE - ±5,350 SF INDUSTRIAL/FLEX CONDO

32 MAUCHLY, SUITE B | IRVINE, CA 92618



PROPERTY FEATURES:

- » ±5,350 SF High-Image Industrial/Flex Condominium in the ADA Technology Park
- » ±3,500 SF of Functional Two-Story Office Space With Great Glass Line
- » Fire Sprinklers
- » Two (2) Ground-Level Loading Doors
- » Potential Signage Visible on Barranca Parkway
- » 3.5:1 Parking Ratio
- » ±21' Warehouse Clear Height
- » 200 Amps of Power, 120/208 Volt, 3-Phase (verify)
- » Excellent Access to the 5 and 405 Freeways, Irvine Spectrum, and Surrounding Retail Amenities
- » Walking Distance to the Irvine Transit Station



CONTACT US:

TIDEMARK
Real Estate Services


**BROKERAGE | INVESTMENTS
PROPERTY MANAGEMENT**

TAYLOR SNYDER, MBA
Senior Vice President
(949) 533-1321
taylor@tidemarkrealestate.com
DRE Lic. 02092420


PAT LACEY
Executive Director
(714) 875-4134
pat@tidemarkrealestate.com
DRE Lic. 00988663

STEPHEN MARGARETIS
Senior Associate
(949) 439-1988
stephen@tidemarkrealestate.com
DRE Lic. 02112014


DISCLAIMER: The information contained herein has been obtained from the property owner or other third party and is provided to you without verification as to accuracy. We (Tidemark Real Estate Services, Inc., its brokers, employees, agents, principals, officers, directors and affiliates) make no warranty or representation regarding the information, property, or transaction. You and your attorneys, advisors and consultants should conduct your own investigation of the property and transaction.



FIRST STORY FLOOR PLAN



SECOND STORY FLOOR PLAN



CONTACT US:

TIDEMARK
Real Estate Services
BROKERAGE | INVESTMENTS
PROPERTY MANAGEMENT

TAYLOR SNYDER, MBA
Senior Vice President
(949) 533-1321
taylor@tidemarkrealestate.com
DRE Lic. 02092420

PAT LACEY
Executive Director
(714) 875-4134
pat@tidemarkrealestate.com
DRE Lic. 00988663

STEPHEN MARGARETIS
Senior Associate
(949) 439-1988
stephen@tidemarkrealestate.com
DRE Lic. 02112014

DISCLAIMER: The information contained herein has been obtained from the property owner or other third party and is provided to you without verification as to accuracy. We (Tidemark Real Estate Services, Inc., its brokers, employees, agents, principals, officers, directors and affiliates) make no warranty or representation regarding the information, property, or transaction. You and your attorneys, advisors and consultants should conduct your own investigation of the property and transaction.