



UNIT W30
3,732 SF



Verify rough locations of demising and interior
of utilities within the premise. This
cautions of said items above. It is incumbent
ent to verify the existing conditions and their
completion of their design documents.
responsible for any costs or delays. Tenant may
required field verification.

UNIT 20
3,732 SF