



admin@petrocomplianceservices.com

+1 561-894-9965

APPENDIX C-1 | TANK SECONDARY CONTAINMENT INTEGRITY TESTING DRY TEST METHOD

Facility Name:	Stricklands One Stop Mart		Owner:	Mid Florida petroleum		
Address:	6023 Kingsley Lake Dr		Address:	6023 Kingsley Lake Dr		
City, State, Zip Code:	Starke		City, State, Zip Code:	Starke		
Facility I.D. #:	8519274		Phone #:	352-214-1436		
Testing company:	Petro compliance services		Phone #:	561-523-4161	Dated:	08/13/2026
This data sheet is for testing integrity of the dry secondary containment of a UST. See PEI/RP1200, Section 4.2 for the test procedure.						
Tank number	3	4				
Tank material	FIBERGLASS CLAD STEEL	FIBERGLASS CLAD STEEL				
Product stored	REGULAR	REGULAR				
Tank capacity*, gallons	3000	3000				
Test start time	18:30	16:00				
Initial vacuum reading, inches Hg (See Table 4-1 below.)	6	6				
Specified test duration (See Table 4-1 below.)	1 hr	1 hr				
Test end time	19:30	17:00				
Final vacuum reading, inches Hg	2	6				
Is the annular space dry after the test?	No	Yes				
Test result	Fail	Pass				
Table 4-1 Test parameters						
	Tank Type	Vacuum inches Hg	Capacity, gallons	Duration hours	undefined	undefined
	Fiberglass	10	<20,000	1	undefined	undefined
	Fiberglass	10	20,000+	2	undefined	undefined
	Steel	6	<20,000	1	undefined	undefined
	Steel	6	20,000+	2	undefined	undefined
*Total tank capacity, including all compartments in a multi-compartment tank.						
Comments:	TANK 3 FAILED THE BREACH OF INTEGRITY TEST. TANK 3 ANNULAR SPACE IS GETTING WATER SLOWLY.					

Tester's Name: Muhammad Ilyas

Tester's Signature: 