



# FIRE EXTINGUISHER SALES & SERVICE INC.

31551 GROESBECK HIGHWAY, FRASER, MICHIGAN 48026-2550  
 PHONE: (586) 293-7575, FAX: (586) 293-0145, E-MAIL: sales@mifess.com

## FIRE SPRINKLER INSPECTION REPORT

Conferred With Liz Pendleton Inspection Report No.: 07182024 A/C 7889 16591

REPORT TO: PRAET TOOL & ENGINEERING DATE: July 18, 2024  
 STREET: 51214 INDUSTRIAL DRIVE INSPECTOR: Dorian Hatchett  
 CITY & STATE: MACOMB TOWNSHIP, MICHIGAN 48042 JOB PHONE: 586-677-3800  
lpendleton@praettool.com

Number of risers One Wet Riser Fire Dept. Phone No. 586-286-0030

10 Date dry-pipe valve trip tested (control valve fully open) N/A (See Trip Test Table which follows.)  
 11 Date quick-opening device tested N/A (See Trip Test Table which follows.)

TRIP TEST TABLE												
DRY VALVE					Q.O.D.							
Make		Model		Serial No.	Make		Model		Serial No.			
Dry Pipe Operating System Test	Without Q.O.D.	Time to Trip thru Test Pipe		Water Pressure	Air Pressure		Trip Point Air Pressure		Time water reached Test Outlet		Did Fire Alarm Operated Properly	
		MIN.	SEC.	PSI	PSI	PSI	MIN.	SEC.	YES	NO		

12 See Control Valve Maintenance Table L = Locked    C = Chained    TS = Tamper Switch

CONTROL VALVE MAINTENANCE TABLE							
Control Valves	Number	Size	Type	Open	Secured	Operated	Comments
City Connection Valve	1	6"	NRS	YES	N/A	N/A	IN GATE WELL
Header Control Valve	1	4"	OS&Y	YES	TS/C	YES	
Riser 1 Control Valve	1	4"	OS&Y	YES	TS/C	YES	
Elevator Control Valve	1	1"	BFV	YES	NO	YES	
Paint Booth Control Valve	1	1.5"	OS&Y	YES	NO	YES	

13 Water Flow Test at Sprinkler Riser  
 Water Supply Source: City  Tank  Pump

	Date	Test Pipe Location	Size of Test Pipe	Static Pressure PSI	Residual (Flow) Pressure PSI
Last water flow test	8/15/2023	AT THE MAIN	2"	55/45	40
This water flow test	7/18/2024	At the Main	2"	50/45	50

15 Are Fire Extinguishers Present & how many? **12** Yes  No  Date last inspected? July 18, 2024  
 16 Are Fire Suppression Systems Present? Yes  No  Date last inspected? \_\_\_\_\_  
 17 Is a Back Flow Systems Present? Yes  No  Date last inspected? August 10, 2023

18 Adjustments or corrections made during this inspection: \_\_\_\_\_  
 19 Although these comments are not the result of an engineering review, the following desirable improvements are recommended: \_\_\_\_\_

20 last serviced by: Fire Extinguisher Sales & Service

Signature Dorian Hatchett Date: July 18, 2024

# Annual Sprinkler Report



Report # SPI - 1006776

## General Information

Service Provider:	Fire Extinguisher Sales & Service, Inc.	SP ID:	SP11307
Customer Account #:			
Address:	31551 Groesbeck Hwy Fraser MI 48026		
Phone:	586-293-7575-	Fax:	--
General Email:	sales@mifess.com		
Report Entered By:	--	User's Email:	sales@mifess.com
SP Lead Technician:	DORIAN HATCHETT	Date Inspection Completed:	2024-07-18
Lead Tech Nicet #:	--		
Other License #:	--	Other License Type:	--

Primary AHJ's Name:	Fraser Fire	Primary AHJ ID:	MIA11391
Primary AHJ Phone:	586-293-2000	Primary AHJ Email:	gilliesj@fraserdps.com

PO ID:	--		
Business Occupant:	Praet Tool & Engineering		
Region:	--	Location:	Praet Tool & Engineering
Number:	51214	Street Prefix:	--
Street Name	Industrial Drive	Unit #:	--
City:	Macomb	State:	MI
Zip:	48042-4025		
Contact Name:	Liz Pendleton		
Contact Phone:	586-677-3800	Contact Email:	lpendleton@praettool.com
PIN#:	--	Classification:	--

## Attach Report

Report Status:	Compliant
Report:	SPI - Sprinkler
Frequency:	Annual
Attachment:	There is a supplemental file for this report that is not available in PDF view. Please visit <a href="http://inspectionreportsonline.net">inspectionreportsonline.net</a> to access that file.
Next Inspection Due Date:	2025-07-18
Report Completed By:	--
Email Sent To:	lpendleton@praettool.com

## Notes

None

## Supplemental Attachments

None

Test performed in accordance with the following code or standard: --